Abbe-Diagram $n_d - \nu_d$

Description of Symbols

- N-glasses
- P-glasses
- Classical crown and flint glasses
- Glasses available as N-glasses or classical flint glasses
- Glasses suitable for precision molding
- HT – High transmittance glasses
- HTultra – Ultra high transmittance glasses
- * Available in step 0.5