
Abbe-Diagram n_d–ν_d
Description of Symbols
N-glasses
P-glasses
Classical crown and flint glasses
Glasses available as N-glasses or classical flint glasses
Glasses suitable for precision molding
HT – High transmittance glasses
HTultra – Ultra high transmittance glasses
* Available in step 0.5
ν_d
n_d
LASF
SF
LAF
LAK
BASF
SSK
BAF
SK
PSK
BALF
BAK
LF
F
LLF
KF
PK
BK
K
FK
SCHOTT
glass made of ideas
January 2018